

Fabrication and Evaluation of Welded Ti-6Al-4V Test Sections

by Scott Grendahl, Daniel Snoha, and Brijmohan Roopchand

ARL-TR-2533

June 2001

Approved for public release; distribution is unlimited.

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Citation of manufacturer's or trade names does not constitute an official endorsement or approval of the use thereof.

Destroy this report when it is no longer needed. Do not return it to the originator.

Army Research Laboratory

Aberdeen Proving Ground, MD 21005-5069

ARL-TR-2533

June 2001

Fabrication and Evaluation of Welded Ti-6Al-4V Test Sections

Scott Grendahl and Daniel Snoha

Weapons and Materials Research Directorate, ARL

Brijmohan Roopchand

U.S. Army Armament Research, Development, and Engineering Center

Approved for public release; distribution is unlimited.

Abstract

There has been wide support for the continued reduction in weight of heavy armor combat systems. Of course no one is willing to give up performance with this reduction in weight. This program investigated the feasibility of utilizing Ti-6Al-4V as an alternate armor material for the M1 Abrams turret glacis as opposed to the presently utilized RHA steel. Two turret glacis test sections were fabricated from Ti-6Al-4V armor plate, and one was fabricated from RHA steel. These sections were ballistic tested vs. common threats. The weld joint design is described from a theoretical basis as well as functional performance. The ballistic results of all test sections are discussed in detail, and recommendations for future work are provided.

Contents

Lis	t of F	igures	v			
Lis	t of T	ables	vii			
1.	Introduction					
2.	Fab	rication of the ARL Test Section	1			
3.	Join	at Designs	2			
4.	AR	L Test Section Ballistic Results	2			
	4.1	Discussion of ARL Ballistic Testing	8			
	4.2	Fabrication of the GDLS Test Section	9			
5.	GD	LS Test Section Ballistic Results	9			
	5.1	Discussion of GDLS Ballistic Testing	11			
	5.2	Assessment of ARL Weld Joints	12			
6.	Ten	sile Testing	27			
7.	Che	emistry	28			
8.	Conclusions					
Dis	Distribution List 2					
Rei	ort T	Occumentation Page	31			

INTENTIONALLY LEFT BLANK.

List of Figures

Figure 1. Schematic of the front plate to top plate weld joint	
Figure 2. Schematic of the front plate to side plate weld joint	
Figure 3. Schematic of the front plate to base plate weld joint	
Figure 4. Schematic of back plate to top plate weld joint	4
Figure 5. Schematic of back plate to side plate weld joint.	4
Figure 6. Schematic of the top plate to side plate weld joint	
Figure 7. ARL overview, schematic 1.	6
Figure 8. ARL overview, schematic 2.	θ
Figure 9. ARL overview, schematic 3.	
Figure 10. Photograph of the tertiary cracking along the base plate of the ARL test section.	
Figure 11. Schematic of the redesigned front to base plate weld joint	8
Figure 12. GDLS overview, schematic 1.	9
Figure 13. Design of GDLS back to top plate weld vs. test section	9
Figure 14. Photograph of the GDLS test section back to top and back to side weld designs	
Figure 15. GDLS overview, schematic 2	11
Figure 16. Photograph of the GDLS test section failure of the base plate	11
Figure 17. Macro cross section of the front plate to top plate weldment	12
Figure 18. Cross section of the front plate to top plate weld bead	13
Figure 19. Cross section showing a fine crack in the front plate to top plate weldment.	13
Figure 20. Front to top plate fusion zone with grain growth across weld pass boundaries.	14
Figure 21. Front plate to top plate weldment showing approximately 1/8-in HAZ.	14
Figure 22. Macro cross section of the front to side plate weldment	
Figure 23. Cross section depicting the front to side plate fusion zone	
Figure 24. Front to side plate weld root.	16
Figure 25. Front to side plate middle of the fusion zone	

Figure 26. Front to side plate weld cap	17
Figure 27. Macro cross section of the front to base plate	17
Figure 28. Cross section of the front to base plate fusion zone	
Figure 29. Cross section of the front to base plate weld root	
Figure 30. Cross section of the middle of the fusion zone of the front to base plate weld	19
Figure 31. Cross section of the front to base plate weld cap	19
Figure 32. Macro cross section of the back to top plate	
Figure 33. Cross section of the back to top plate weld fusion zone	
Figure 34. Cross section of the root of the back to top plate weldment	
Figure 35. Cross section of the middle of the fusion zone of the back to top plate weldment.	21
Figure 36. Cross section of the cap of the back to top plate weldment	22
Figure 37. Macro cross section of the base to side plate weldment	
Figure 38. Cross section of the back to side plate weld fusion zone	
Figure 39. Cross section of the root of the back to side plate weldment	
Figure 40. Cross section of the middle of the back to side plate weld fusion zone	24
Figure 41. Cross section of the back to side plate weld cap	24
Figure 42. Macro cross section of the top to side plate weldment	
Figure 43. Cross section of the top to side plate weld fusion zone	
Figure 44. Cross section of the root of the top to side plate weldment	
Figure 45. Cross section of the middle of the top to side plate weld fusion zone	26
Figure 46. Cross section of the cap of the top to side plate weldment	27

List of Tables

Table 1. Tensile res	ults from the ARL Ti-6-4 test section	27
	GD test section chemistry results for heat R33	

INTENTIONALLY LEFT BLANK.

1. Introduction

The U.S. Army Tank-automotive and Armament Command (TACOM), Tank Automotive Research Development and Engineering Center (TARDEC) initiated a program through the titanium MANTECH program to evaluate the feasibility of creating a functional titanium test section representing part of an M1 Abrams turret. The test section simulating the M1 turret glacis was developed jointly by the M1 PM office, General Dynamics Land Systems (GDLS), and the U.S. Army Research Laboratory (ARL) Weapons and Materials Research Directorate (WMRD). The test section was designed to contain a classified armor package. Both GDLS and ARL-WMRD separately designed and created Ti-6Al-4V test sections for evaluation. Additionally, GDLS created an RHA test section. Since the GDLS design would be proprietary, TACOM wanted ARL-WMRD to support the program by creating a separate test section. Both titanium designs, as well as an RHA test section, included the identical armor package and were tested against a KE, CE, and shock projectile. The approximate size of the test sections was 63 × 38 × 28 in.

2. Fabrication of the ARL Test Section

The titanium plate utilized by ARL-WMRD was Ti-6Al-4V (ASTM Grade 5) manufactured by Timet (Titanium Metals Corporation) and procured through TACOM. The plates were manufactured from 34-in vacuum arc remelt (VAR) ingots from heat no. R3392. Based on prior experience with joining titanium, ARL chose to plasma cut the sides and the top of the test section and use conventional machining for the front and back. The backing strips for the welds were water jet cut. After several design iterations, it was decided that joints would be modified from full machining with interlocking steps. modification included the incorporation of tacked on backing strips to maximize the cross-sectional area of the weld and to minimize the machining necessary to maintain the test schedule of the program. Schematics of the individual joint designs are included in the next section of this report. All joints were ground with silicon carbide grinding wheels and solvent (normalized propyl bromide) cleaned prior to welding. The latter was more than likely superfluous. Plates exceeding 1 in were preheated to 125 °F prior to welding. Backing strips were tack welded onto the plates prior to final assembly to prevent the root pass from experiencing arc blow through, contain shield gases, and aid in assembly of the structure. The welds were fabricated with 0.045-in extra low interstitial (ELI) titanium wire. ELI wire was utilized to provide extra ductility within the welds.

A 3-in trailing shield and backing shield were utilized when appropriate, in conjunction with 100% argon shielding gas. Interpass temperature was kept within 250 °F between all passes. Each pass was made at 20–25 in/min forehand travel, and was cleaned with a stainless wire brush before applying the next weld. All weld starts and stops were ground with tree-shaped tungsten carbide burrs on a rotary tool. The weld process utilized was pulse metal inert gas (MIG) at 300 A, and the wire feed was approximately 800 ft/min.

3. Joint Designs

The ARL-WMRD joint designs incorporated 60° openings (when feasible) and backing strips to prevent arc blow through. Lands of 1/8 in were specified at the roots of the welds. Figures 1–6 present the schematics of the joint designs of the ARL-WMRD test section. The schematics are not drawn to scale. The weld joints between the sides and the base were fillet welds.




Figure 1. Schematic of the front plate to top plate weld joint.

4. ARL Test Section Ballistic Results

The first ballistic shot was a KE round that completely penetrated the target. The second round, a CE round, left only a 1/2-in penetration hole in the back plate,




Figure 2. Schematic of the front plate to side plate weld joint.




Figure 3. Schematic of the front plate to base plate weld joint.




Figure 4. Schematic of back plate to top plate weld joint.




Figure 5. Schematic of back plate to side plate weld joint.




Figure 6. Schematic of the top plate to side plate weld joint.

but was still considered a penetration. The third and final round was a shock round to test the weld toughness, the result of which was considerable cracking. The ARL section had its primary fracture from this round at the top back left hand side (LHS) of the box, point A in Figure 7. Inspection revealed that the inside surface of the top plate in that area had taken an impact load from the armor package during the ballistic event (See GDLS Test Section Ballistic Results). Consequently, the top plate to back plate joint failed from overpressure down a 23-in span, point A, along the weld. The top 1/4-1/2 in of this weld zone failed in shear. Beyond this region, cracking advanced out of the weld joint and proceeded into the base material of the top plate, most likely as a result of the lifting hook being welded across the plate interface in this area (see schematic). Cracking progressed through the top plate, until the right hand side (RHS) of the top to side plate joint was reached at the approximate halfway point (Figure 7, point B). The crack then turned and followed the top to side plate joint approximately 6 in before arresting. The other end of the crack, emanating from the primary fracture, met (at the top back LHS corner, point C) with a crack from a secondary fracture that initiated at the base of the LHS gusset support (Figures 7 and 8, point D). In all likelihood, cracking originated from this area due to the fact that several weld beads converge here. This area was almost directly behind the point of collision of the round as it impacted the back plate (or impacted the armor package that, in turn, impacted the back plate). Failure most likely occurred here because the weld beads were discontinuous in this area.

The secondary fracture, crack no. 1 in Figure 8, ran along the back to bottom plate interface and continued approximately 30 in until it arrested. Crack no. 2 proceeded to the LHS (from front orientation) bottom back corner and wrapped




Figure 7. ARL overview, schematic 1.




Figure 8. ARL overview, schematic 2.

around the edge of the box. It then split in two, cracks 2A and 2B. Crack 2A proceeded along the LHS to the bottom weld interface approximately 15 in where it arrested. Crack 2B ran along the LHS back to the side weld interface and curled around the top of the plate where it met with the crack from the primary fracture and arrested. Crack no. 3 proceeded directly into the base material of the LHS gusset and ran entirely through the support; Figure 8 shows the details.

Tertiary fracture occurred entirely within the base plate material from the entry of the shock round in the front plate. The 1-in-thick base plate failed along a 14-in section due to the bending moment and stresses from the impacting projectile. This can be observed in Figure 9, point E, and in Figure 10. This crack can most likely be eliminated from a simple redesign of the front to base plate weld and would not occur on a vehicle due to the joint design differences.




Figure 9. ARL overview, schematic 3.




Figure 10. Photograph of the tertiary cracking along the base plate of the ARL test section.

4.1 Discussion of ARL Ballistic Testing

The tertiary fracture occurred first, but is of the least significance. It was ARL's understanding that during the construction of the test section, the base plate needed a lip around the box so it could be held in place on the test stand. A tank turret would not need this lip nor incorporate it in its design. Figure 11 depicts a simple redesign of the front to bottom weld interface that would change the stress configuration, drastically reducing the likelihood of cracking in this area.




Figure 11. Schematic of the redesigned front to base plate weld joint.

The secondary fracture most likely occurred from a combination of a lack of weld material along the back to base plate interface and the stop/start point of six weld root passes being in the corner of the gusset. A redesign of the welding in this area would result in the entire back plate to base plate interface being welded before the addition of the gusset supports. The fact that the GDLS test section had more weld metal in this area, a very similar weld design, continuous weld beads, and minimal cracking in this area substantiates this (See GDLS Test Section Ballistic Results). The main point here is that ARL believes the cracking originated from a fault in the welding procedure (discontinuous weld beads), not from a fault in the weld design.

The primary fracture occurred as a result of overpressure. This indicates that the weld was not tough (a measure of both strength and ductility) enough to stop cracking from initiating. Preventing crack initiation can eliminate crack progression. The results of the other welds on both the ARL and GDLS test section (in the case of the back plate to bottom plate interface discussed previously) indicate a nearly functional weld process. However, the stresses on the top plate to back plate interface still need to be lowered. In the opinion of ARL, the top plate should be increased in thickness to approximately 1.5 in to allow for a larger weld area to reduce the stress at this interface. It should be noted that the RHA box also had significant cracking (10–15 in) in this area.

4.2 Fabrication of the GDLS Test Section

The GDLS test section was fabricated from heat R2494 Timet Ti-6Al-4V material. The exact procedure is not known.

5. GDLS Test Section Ballistic Results

The GDLS test section had its primary fracture originate at the top back LHS of the box, point A in Figure 12.




Figure 12. GDLS overview, schematic 1.

It was apparent that the inside surface of the top plate in that area had taken an impact load from the armor package. There were linear deformation marks on the inside surface of the top plate that matched the configuration of the armor package. Additionally, the GDLS box weld interface did not match the proposed design of the region, as observed in the picture of the weld failure (see Figures 13 and 14). The top to back plate interface was designed as shown in Figure 13, however; the test section also had an extra step shown.




Figure 13. Design of GDLS back to top plate weld vs. test section.




Figure 14. Photograph of the GDLS test section back to top and back to side weld designs.

This extra step was detrimental to the strength of the weld. As a result, the top plate to back plate weld failed from overpressure along a 46-in span along the weld (2/3 of the welded length). The top 1/4–1/2 in of this weld zone failed in shear. There also existed overpressure failure along a 10-in span on the back LHS of the top to side plate interface (see Figure 12, point B). Beyond these regions, the crack paths continued along the top plate welds until both crack fronts met at the top front RHS of the box and the top plate was entirely removed in one piece. A crack then proceeded into the RHS side plate base material, diagonally through the air vent in the RHS side plate, and arrested at the back bottom RHS corner of the test section.

The secondary fracture occurred along the inside back to LHS side plate and back to base plate interfaces. The back to side plate failure originated from overpressure along a 17-in section toward the bottom of that interface (see Figure 15, point C). Cracks progressed along the back to bottom plate weld interface. From the other end of the overpressure zone, cracking advanced into the base material of the LHS side plate until it met the crack path of the top plate from the primary failure (see Figure 15, point D).

Finally, since both sides of the box were in some way fractured, there was nothing to prevent the box from folding back on itself (except the strength of the bottom plate). The gussets supported the back plate, and since the bottom plate was already weakened by the crack along the back plate to bottom plate interface, the bottom plate failed catastrophically at its interface with the back plate (see Figure 16).




Figure 15. GDLS overview, schematic 2.




Figure 16. Photograph of the GDLS test section failure of the base plate.

5.1 Discussion of GDLS Ballistic Testing

Several separate areas of overpressure existed after the shock testing. Some of these areas were also of significant size. The areas where the overpressure mode of failure existed need improvement in the weld toughness and strength. Redesigning the welds, changing the weld material, and/or optimizing the welding process and parameters can accomplish this.

5.2 Assessment of ARL Weld Joints

Six of the weld joints were assessed after ballistic testing. Metallography and tensile testing were performed, including both transverse and longitudinal tensile tests. Kroll's reagent was utilized to reveal the grain structure of the base material and the weldment. The multiple pass weld technique can clearly be observed in the photographs. The weldments contained a heat affected zone (HAZ) of approximately 1/8 inch in size bordering the weld fusion zone. The HAZ consisted of equiaxed primary α and β with some β decomposition products. The weld fusion zone revealed epitaxial grain growth through the multiple passes. The microstructure consisted of retained β and β decomposition products most likely including Widmanstatten α and β , massive α , and α' and α'' martensites, although these were not confirmed through electron microscopy.

Figures 17–21 depict the cross sections of the front plate to top plate weld joint, as shown schematically in Figure 1. Figures 22–26 depict the front to side plate weld cross sections, as shown schematically in Figure 2.




Figure 17. Macro cross section of the front plate to top plate weldment.




Figure 18. Cross section of the front plate to top plate weld bead.




Figure 19. Cross section showing a fine crack in the front plate to top plate weldment.




Figure 20. Front to top plate fusion zone with grain growth across weld pass boundaries.




Figure 21. Front plate to top plate weldment showing approximately 1/8-in HAZ.




Figure 22. Macro cross section of the front to side plate weldment.




Figure 23. Cross section depicting the front to side plate fusion zone.




Figure 24. Front to side plate weld root.




Figure 25. Front to side plate middle of the fusion zone.




Figure 26. Front to side plate weld cap.

Figures 27–31 depict the front to base plate weld cross sections, as shown schematically in Figure 3, while Figures 32–36 depict the base to top plate weld cross sections, as shown schematically in Figure 4.

Figures 37--41 depict the base to side plate weld cross sections, as shown schematically in Figure 5.

Similarly, Figures 42–46 depict the top to side plate weld cross sections, as shown schematically in Figure 6.




Figure 27. Macro cross section of the front to base plate.




Figure 28. Cross section of the front to base plate fusion zone.




Figure 29. Cross section of the front to base plate weld root.




Figure 30. Cross section of the middle of the fusion zone of the front to base plate weld.




Figure 31. Cross section of the front to base plate weld cap.




Figure 32. Macro cross section of the back to top plate.




Figure 33. Cross section of the back to top plate weld fusion zone.




Figure 34. Cross section of the root of the back to top plate weldment.




Figure 35. Cross section of the middle of the fusion zone of the back to top plate weldment.




Figure 36. Cross section of the cap of the back to top plate weldment.




Figure 37. Macro cross section of the base to side plate weldment.




Figure 38. Cross section of the back to side plate weld fusion zone.




Figure 39. Cross section of the root of the back to side plate weldment.




Figure 40. Cross section of the middle of the back to side plate weld fusion zone.




Figure 41. Cross section of the back to side plate weld cap.




Figure 42. Macro cross section of the top to side plate weldment.




Figure 43. Cross section of the top to side plate weld fusion zone.




Figure 44. Cross section of the root of the top to side plate weldment.




Figure 45. Cross section of the middle of the top to side plate weld fusion zone.




Figure 46. Cross section of the cap of the top to side plate weldment.

6. Tensile Testing

Weldments of the ARL test section were set aside for tensile testing. Tensile testing was performed on the weldments of test section in both the longitudinal (all weld metal) and transverse directions. Five specimens were prepared and tested in each direction. Yield strength, tensile strength, elongation, and reduction in area were all recorded. Table 1 depicts the results of the work.

Table 1. Tensile results from the ARL Ti-6-4 test section.

Specimen			Yield	Tensile		Reduction
Number	Diameter	Area	Strength	Strength	Elongation	in Area
	(in)	(in²)	(ksi)	(ksi)	(%)	(%)
Trans. 1	0.252	0.0499	145	148	8	12
Trans. 2	0.252	0.0499	131	147	6	8
Trans. 3	0.252	0.0499	132	148	8	12
Trans. 4	0.252	0.0499	132	150	7	9
Trans. 5	0.252	0.0499	133	151	9	9
Long. 1	0.250	0.0491	130	145	6	9
Long. 2	0.251	0.0495	133	141	7	12
Long. 3	0.252	0.0499	131	143	7	8
Long. 4	0.252	0.0499	128	142	8	16
Long. 5	0.252	0.0499	134	148	9	10

7. Chemistry

The chemistry of the titanium heat utilized to fabricate the material of the test section is included for convenience in Table 2.

Table 2. ARL and GD test section chemistry results for heat R3392 and R2494.

L		Fe	С	N	0	Н	Al	V	Sn	Zr	Мо	Cr	Cu	Ni	Pd
	R3392	0.016	0.022	0.009	0.175	0	6.15	3.95	0.005	0.003	0.008	0.000	0.003	0.000	0.000
	R2494	0.185	0.024	0.009	0.170	0	6.505	3.935	0.005	0.006	0.011	0.000	0.004	0.000	0.000

8. Conclusions

The fabrication and ballistic testing of a titanium test section was completed. The subsequent analysis showed that while there was considerable cracking of some of the weldments, potential exists for using titanium as a tank turret material. While it was not a goal of this program to optimize a welding process for Ti-6Al-4V, the weld design and process utilized by ARL proved more effective than the corresponding GDLS design and process. Based upon the fact that both titanium test sections and the RHA test section cracked significantly when subjected to the shock round, it is suggested that more optimization work is needed for both the design of the weld joints and the welding process for titanium. However, the effort should not be abandoned based on these results.

NO. OF <u>COPIES</u> <u>ORGANIZATION</u>

- 2 DEFENSE TECHNICAL INFORMATION CENTER DTIC OCA 8725 JOHN J KINGMAN RD STE 0944 FT BELVOIR VA 22060-6218
- 1 HQDA DAMO FDT 400 ARMY PENTAGON WASHINGTON DC 20310-0460
- 1 OSD
 OUSD(A&T)/ODDR&E(R)
 DR R J TREW
 3800 DEFENSE PENTAGON
 WASHINGTON DC 20301-3800
- 1 COMMANDING GENERAL US ARMY MATERIEL CMD AMCRDA TF 5001 EISENHOWER AVE ALEXANDRIA VA 22333-0001
- 1 INST FOR ADVNCD TCHNLGY THE UNIV OF TEXAS AT AUSTIN 3925 W BRAKER LN STE 400 AUSTIN TX 78759-5316
- 1 DARPA SPECIAL PROJECTS OFFICE J CARLINI 3701 N FAIRFAX DR ARLINGTON VA 22203-1714
- 1 US MILITARY ACADEMY
 MATH SCI CTR EXCELLENCE
 MADN MATH
 MAJ HUBER
 THAYER HALL
 WEST POINT NY 10996-1786
- 1 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRL D
 DR D SMITH
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197

NO. OF COPIES ORGANIZATION

- 1 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRL CI AI R
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 3 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRL CI LL
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 3 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRL CI IS T
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197

ABERDEEN PROVING GROUND

2 DIR USARL AMSRL CI LP (BLDG 305)

NO. OF <u>COPIES</u> <u>ORGANIZATION</u>

3 PM CRUSADER
SFAE GCSS CR E
BLDG 171A
B ROOPCHAND
PICATINNY ARSENAL NJ
07806-5000

ABERDEEN PROVING GROUND

30 DIR USARL AMSRL WM MD S GRENDAHL

REPORT DO	Form Approved OMB No. 0704-0188						
Public reporting burden for this collection of inform gathering and maintaining the data needed, and con collection of information, including suggestions for	npleting and reviewing the collection of information reducing this burden, to Washington Headquarters	 Send comments regarding this burns Services, Directorate for Information 	den estimate or any other aspect of this Operations and Reports, 1215 Jefferson				
Davis Highway, Suite 1204, Arlington, VA 22202-430 1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE	3. REPORT TYPE AND					
	June 2001	Final, January 199					
4. TITLE AND SUBTITLE Fabrication and Evaluation of	Welded Ti-6Al-4V Test Section	ons	5. FUNDING NUMBERS 622105AH84				
6. AUTHOR(S) Scott Grendahl, Daniel Snoha,	and Brijmohan Roopchand*						
7. PERFORMING ORGANIZATION NAM U.S. Army Research Laborator ATTN: AMSRL-WM-MD Aberdeen Proving Ground, MI	у		8. PERFORMING ORGANIZATION REPORT NUMBER ARL-TR-2533				
9. SPONSORING/MONITORING AGENC	CY NAMES(S) AND ADDRESS(ES)		10.SPONSORING/MONITORING AGENCY REPORT NUMBER				
U.S. Army Tank-automotive an Business Unit, AMSTA-TR, W		avy Combat Systems					
11. SUPPLEMENTARY NOTES							
*U.S. Army Armament Resear	ch, Development, and Enginee	ering Center, Picatinny	Arsenal, NJ 07806				
12a. DISTRIBUTION/AVAILABILITY STA Approved for public release; di			12b. DISTRIBUTION CODE				
13. ABSTRACT (Maximum 200 words)							
There has been wide support for the continued reduction in weight of heavy armor combat systems. Of course no one is willing to give up performance with this reduction in weight. This program investigated the feasibility of utilizing Ti-6Al-4V as an alternate armor material for the M1 Abrams turret glacis as opposed to the presently utilized RHA steel. Two turret glacis test sections were fabricated from Ti-6Al-4V armor plate, and one was fabricated from RHA steel. These sections were ballistic tested vs. common threats. The weld joint design is described from a theoretical basis as well as functional performance. The ballistic results of all test sections are discussed in detail, and recommendations for future work are provided.							
14. SUBJECT TERMS		15. NUMBER OF PAGES					
titanium, welding, mechanical		38 16. PRICE CODE					
17. SECURITY CLASSIFICATION 1	8. SECURITY CLASSIFICATION	19. SECURITY CLASSIFICA	ATION 20. LIMITATION OF ABSTRACT				
of REPORT UNCLASSIFIED	of this page UNCLASSIFIED	OF ABSTRACT UNCLASSIFIE					

INTENTIONALLY LEFT BLANK.

USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your comments/answers to the items/questions below will aid us in our efforts.

1. ARL Report Numb	per/Author_ARL-TR-2533 (Grendahl)	Date of Report June 2001
2. Date Report Recei	ved	
-	isfy a need? (Comment on purpose, related projections)	ect, or other area of interest for which the report will be
4. Specifically, how i	s the report being used? (Information source, de	esign data, procedure, source of ideas, etc.)
	-	as far as man-hours or dollars saved, operating costs
	s. What do you think should be changed to impranat, etc.)	ove future reports? (Indicate changes to organization,
	Organization	
CURRENT	Name	E-mail Name
ADDRESS	Street or P.O. Box No.	
	City, State, Zip Code	
7. If indicating a Chan Incorrect address belo		vide the Current or Correct address above and the Old or
	Organization	
OLD	Name	
ADDRESS	Street or P.O. Box No.	
	City, State, Zip Code	
	O amount this about Cold as indicated a	cano alocad and mail)

(Remove this sheet, fold as indicated, tape closed, and mail.)
(DO NOT STAPLE)